





PHOTOGRAPHIC LOG		
Client Name: CPG		Site Location: Lower Passaic River (River Mile 10.9)
Project No. 60270961		
Photo No. 1	Date: 20160121	
Direction Photo Taken: Northwest		
Description: Representative distance of samplers from shore and icy bank conditions (looking towards station 15A-0605). Arrow pointing to location of 15A-0605.		 <p>A photograph of a river with ice and debris. A red arrow points to a location in the distance. The timestamp '1/21/2016 14:00' is visible in the bottom right corner of the photo.</p>

Photo No. 2	Date: 20160121	
Direction Photo Taken: North		
Description: Representative distance of samplers from shore and icy bank conditions (looking towards station 15A-0604). Arrow pointing to location of 15A-0604.		 <p>A photograph of a river with ice and debris, framed by bare branches. A red arrow points to a location in the distance. The timestamp '1/21/2016 14:05' is visible in the bottom right corner of the photo.</p>

PHOTOGRAPHIC LOG		
Client Name: CPG		Site Location: Lower Passaic River (River Mile 10.9)
Project No. 60270961		
Photo No. 3	Date: 20160121	
Direction Photo Taken: East		
Description: Looking upstream from station 15A-0608 at low-tide.		
Photo No. 4	Date: 20160121	
Direction Photo Taken: West		
Description: Station 15A-0601 from shore. Green tagged sampler (underlying sediment) is obscured by debris. Arrow pointing to approximate location of underlying sediment sampler.		



PHOTOGRAPHIC LOG		
Client Name: CPG		Site Location: Lower Passaic River (River Mile 10.9)
Project No. 60270961		
Photo No. 5	Date: 20160121	
Direction Photo Taken: Northwest		
Description: Station 15A-0603 from shore. Arrow pointing to approximate location of red tagged sampler (armor layer), which was not visible from shore.		

Photo No. 6	Date: 20160121	
Direction Photo Taken: Northwest		
Description: Station 15A-0604 from shore. All three samplers present.		



PHOTOGRAPHIC LOG		
Client Name: CPG		Site Location: Lower Passaic River (River Mile 10.9)
Project No. 60270961		
Photo No. 7	Date: 20160121	
Direction Photo Taken: Northwest		
Description: Station 15A-0605 from shore. All three samplers present.		

Photo No. 8	Date: 20160121	
Direction Photo Taken: North		
Description: Station 15A-0606 from shore. Station distance from shore and debris prevented observation of the condition of the samplers.		




PHOTOGRAPHIC LOG		
Client Name: CPG		Site Location: Lower Passaic River (River Mile 10.9)
Project No. 60270961		
Photo No. 9	Date: 20160121	
Direction Photo Taken: North		
Description: Station 15A-0607 and 15A-0607D (duplicate) accessed by foot. The red tagged sampler (armor layer) for 15A-0607 is at an approximate 65 degree angle.		

Photo No. 10	Date: 20160121		
Direction Photo Taken: North			
Description: Station 15A-608 accessed by foot. Right picture showing red tagged sampler's (armor layer) top of well screen is above sediment. Left picture showing red tagged sampler (armor layer) is slightly bent. Green tagged sampler's (underlying sediment) cap is barely visible above sediment.			